MR3287-12 Serial No. 10/773,399 Response to Office Action dated 4 August 2004

AMENDMENT TO THE CLAIMS

The following listing of claims will replace all prior versions, and listings of claims in the application:

LISTING OF CLAIMS

Claim 1 (Currently amended): A screw comprises a head, a shank under extending from the head in a whole body, and a thread helically built upon the an outside trunk of the shank, wherein, said thread projected from the circular trunk of the shank is consisted of an upper flight flank, a low flight flank, and an peak edge on the joint line of the upper and low flights flanks, and an even number of axial slots are formed on in the thread. The feature is that every each axial slot is beveled with a back angle to form a tilt surface sheared section relative to from the upper flight flank and to the low flight flank so as to form a cutting edge from which the tilt surface and the low flank extend. for facilitating to rapid fastening with smaller tapping torque as tapping in.

BEST AVAILABLE COPY

This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the it	ems checked:
☐ BLACK BORDERS	
☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES	_
☐ FADED TEXT OR DRAWING	•
☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING	
☐ SKEWED/SLANTED IMAGES	
☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS	
GRAY SCALE DOCUMENTS	
☐ LINES OR MARKS ON ORIGINAL DOCUMENT	
☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR	QUALITY
OTHER:	

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.